

Chart P2: Hardness, H , against melting temperature, T_m

The match between process and material is established by the link to material class of Chart P1 and by the use of the melting point–hardness chart shown here. The melting point imposes limits on the processing of materials by conventional casting methods. Low melting point metals can be cast by any one of many techniques. For those which melt above 2000 K, conventional casting methods are no longer viable, and special techniques such as electron-beam melting must be used. Similarly, the yield strength or hardness of a material imposes limitations on the choice of deformation and machining processes. Forging and rolling pressures are proportional to the flow strength, and the heat generated during machining, which limits tool life, also scales with the ultimate strength or hardness. Generally speaking, deformation processing is limited to materials with hardness values below 3 GPa. Other manufacturing methods exist which are not limited either by melting point or by hardness. Examples are: powder methods, CVD and evaporation techniques, and electro-forming.

The chart presents this information in graphical form. In reality, only part of the space covered by the axes is accessible: it is the region between the two heavy lines. The hardness and melting point of materials are not independent properties: low melting point materials tend to be soft; high melting point materials are generally hard. This information is captured by the equation

$$0.03 < \frac{H\Omega}{kT_m} < 20$$

where Ω is the atomic or molecular volume and k is Boltzmann's Constant (1.38×10^{-26} J/K). It is this equation which defines the two bold lines.

