## Chart P3: Volume, V, against slenderness, S

Manufacturing processes vary widely in their capacity to make thin, slender sections. For our purposes, slenderness, S, is measured by the ratio  $t/\ell$  where t is the minimum section and  $\ell$  is the large dimension of the shape: for flat shapes,  $\ell$  is about equal to  $\sqrt{A}$  where A is the projected area normal to t. Thus

$$S = \frac{t}{\sqrt{A}}$$

Size is defined by the minimum and maximum volumes of which the process is capable. The volume, V, for uniform sections is, within a factor of 2, given by

$$V = At$$

Volume can be converted approximately to weight by using an 'average' material density of 5000 kg/m<sup>3</sup>; most engineering materials have densities within a factor of 2 of this value. Polymers are the exception: their densities are all around 1000 kg/m<sup>3</sup>.

The size-slenderness chart is shown opposite. The horizontal axis is the slenderness, S; the vertical axis is the volume, V. Contours of A and t are shown as families of diagonal lines. Casting processes occupy a characteristic field of this space. Surface tension and heat-flow limit the minimum section and the slenderness of gravity cast shapes. The range can be extended by applying a pressure, as in centrifugal casting and pressure die casting, or by preheating the mould. Deformation processes — cold, warm and hot — cover a wider range. Limits on forging-pressures set a lower limit on thickness and slenderness, but it is not nearly as severe as in casting. Machining creates slender shapes by removing unwanted material. Powder-forming methods occupy a smaller field, one already covered by casting and deformation shaping methods, but they can be used for ceramics and very hard metals which cannot be shaped in other ways. Polymer-forming methods — injection moulding, pressing, blow-moulding, etc. — share this regime. Special techniques, which include electro-forming, plasma-spraying, and various vapour-deposition methods, allow very slender shapes. Joining extends the range further: fabrication allows almost unlimited size and complexity.

A real design demands certain specific values of S and V, or A and t. Given this information, a subset of possible processes can be read off.

